

# MINE INSPECTION REPORTS Q 2 2017

## 2 Quarter inspections 2017

### **OAKTOWN FUELS #1, SUNRISE COAL**

Inspection date(s): 4/19/17

Areas Inspected: surface

Findings/Law Violated:

1. Need to clean belly pan plant feed belt #2 30cfr 77.202

Corrective action taken: corrected

Inspection date(s):

Areas Inspected:

Findings/Law Violated:

- 1.

Corrective action taken:

### **OAKTOWN FUELS #2, SUNRISE COAL**

Inspection date(s): 5/17/17

Areas Inspected: books

Findings/Law Violated:

1. No violations

Corrective action taken: none

Inspection date(s):

Areas Inspected:

Findings/Law Violated:

- 1.

Corrective action taken:

### **CARLISLE MINE, SUNRISE COAL COMPANY**

Inspection date(s): 4/6/17

Areas Inspected: seals

Findings/Law Violated:

1. No violations

Corrective action taken: adjusted curtains at seals

Inspection date(s): 5/25/17

Areas Inspected: surface, shops, fuel area, and old wash house

Findings/Law Violated:

1. No violations non producing

Corrective action taken: none

## **FRANCISCO MINE, PEABODY COAL**

Inspection date(s): 5/9/17

Areas Inspected: surface

Findings/Law Violated:

1. A guard was off grinder in shop. 30cfr 77.400(a)

Corrective action taken: corrected

Inspection date(s): 5/18/17

Areas Inspected: Unit 3, belts, 3A, 3B, 3C, 3D

Findings/Law Violated:

1. #13 roof bolter no pry bar. 30cfr 75.211(d)
2. #7 roof bolter parked next to curtain no flag. 30cfr 75.1403
3. Co detector not working at 7x cut 3B belt. 30cfr 75.340(B)

Corrective action taken: violations corrected.

Inspection date(s):

Areas Inspected:

Findings/Law Violated:

- 1.

Corrective action taken:

Inspection date(s):

Areas Inspected:

Findings/Law Violated:

- 1.

Corrective action taken:

## **FREELANDVILLE WEST, TRIAD COAL COMPANY**

Inspection date(s): 4/19/17

Areas Inspected: surface

Findings/Law Violated:

1. No violations

Corrective action taken: none

Inspection date(s): 6/21/17

Areas Inspected: Surface

Findings/Law Violated:

1. No violations

Corrective action taken: none

RECOMMENDATIONS:

**FREELANDVILLE MINE, TRIAD COAL COMPANY PREP PLANTS #1& #2**

Inspection date(s): 6/22/17

Areas Inspected: surface, plants, belts, equipment

Findings/Law Violated: no violations

1. Not operating at this time.

Corrective action taken: none

**GIBSON MINE, GIBSON COAL COMPANY**

Inspection date(s): 5/2/17

Areas Inspected: surface

Findings/Law Violated:

1. Fire extinguisher out of date at MCC 4. 30cfr 77.1110
2. Guard at head of silo belt truck load out needs secured. 30cfr 77.400(d)

Corrective action taken: all violations noted and corrective action taken.

RECOMMENDATIONS:

**GIBSON MINE, SOUTH**

Inspection date(s): 5/3/17

Areas Inspected: surface

Findings/Law Violated:

1. Fire extinguisher bad at plant roller doors. 30cfr 77.1110
2. Belt structure needs cleaned in plant. 30cfr 77.202
3. Panic bar on door in operation room needs repaired. 30cfr 77.200
4. Fire extinguisher on 3<sup>rd</sup> floor of plant is bad. 30cfr 77.1110
5. Vandco truck has out dated fire extinguisher. 30cfr 77.1110

Corrective action taken: all violations noted and action taken to correct.

RECOMMENDATIONS:

**GOLD STAR MINE**

Inspection date(s): 4/18/17

Areas Inspected: Unit secondary, primary, seals

Findings/Law Violated:

1. No ball on life line in intake at 6x cut 1<sup>st</sup> main south. 30cfr 75.380-7(vi)

Corrective action taken: violation noted and corrective action taken.

## LOG CREEK MINE

Inspection date(s): 4/24/17

Areas Inspected: unit secondary and primary

Findings/Law Violated:

1. No violations

Corrective action taken: none

Inspection date(s): 5/24/17

Areas Inspected: mine surface

Findings/Law Violated:

1. No violations

Corrective action taken: none

RECOMMENDATIONS: clean mine and check all power centers  
High levels of rain in the pit has caused some equipment to be sent off for repair and cleaning.

Inspection date(s): 6/14/17

Areas Inspected: surface

Findings/Law Violated:

1. No violations

Corrective action taken: none